Ensuring ABO Compatibility – Key to Safe Transfusion

Facts :

- Globally ABO-incompatible transfusions are still a frequent cause of serious adverse transfusion reactions.
- Most errors result from human actions and thus may be preventable.
- In two consecutive surveys of ABO incompatible blood transfusion in Japan, out of 226 reported incidences 118 were because of identification error between patient and blood product.
- In a survey of America's Blood Centers they found that out of 42 reported ABO incompatible transfusions 26 occurred at patient's bedside.
- Majority of adverse events occur outside the blood bank, which suggests that hospital wide efforts are required to minimize ABO-incompatible transfusions.

Most Hemolytic Transfusion Reactions and resultant deaths are because of inadvertent administration of ABO-incompatible red cells. Such transfusions result from errors in sample or patient identification. In order to prevent life threatening Hemolytic Transfusion Reactions because of ABO-incompatible blood transfusion bedside ABO and Rh grouping of patient and donor's blood unit should be incorporated in pre transfusion testing.

Introducing....

ERYCARD™ 2.0

Blood Grouping Card for ABO and Rh grouping with Autocontrol.



- Blood Grouping in less than 5 minutes
- Easy 3 Step procedure
- Simple interpretation of results
- Auto control for test validation
- Room temperature storage

Applications

- Bed Side ABO & Rh testing of Patient and Donor's blood unit before transfusion.
- Donor's Blood Group Screening in outdoor donation camps.
- Outdoor Blood Grouping Camps.
- Laboratory testing.
- Preconfirmation test, especially at Nursing Homes.
- For releasing compatible blood for Emergency transfusions in
  • Defence Camps • Ambulance • Casualty Services

Ensuring Safe Transfusion...

Ordering Information :

ERYCARD™ 2.0	24 Tests	Cat No. 102800024
ERYCARD™ Micropipette	5µl	Cat No. ECMP00005
ERYCARD™ Micropipette Tip	100 Nos.	Cat No. ECMPT0100

ISO 13485
Certified Company

For further information contact :

TULIP DIAGNOSTICS (P) LTD.

Gitanjali, Tulip Block, Dr. Antonio do Rego Bagh, Alto Santacruz, Bambolim Complex Post Office, Goa - 403 202, INDIA.
Tel.: +91 832 2458546-50 **Fax :** +91 832 2458544 **E-mail :** sales@tulipgroup.com **Website :** www.tulipgroup.com

ERY/LIT/05-24/VER-03